Hovember 24, 1972

Mr. John Schmidt
Division of Industrial Wastes
and Erosion Control
Fulton National Building
12th Floor Box 2063
Harrisburg, Fa. 17120

RE: Industrial Waste William Dick Lagoons West Caln Township Chester County

Dear Mr. Schmidt:

In response to your request concerning the adequacy of vegetative cover at the William Dick Lagoon site, another inspection was made on November 22, 1972, by Rick Casson, Environmental Protection Specialist, and myself.

It is apparent that the area had been reseeded recently, bowever, I do not feel that this reseeding has been very effective, mainly because of the condition of the soil, which is very rocky with little or no topsoil.

Matural revegetation has covered approximately one-fourth area, but the remainder has very sparse cover or no cover at all. Some mild erosion has occurred at the eastern portion of the site.

AR100107

Page 2 Mr. John Schmidt November 24, 1972

It appears that the natural field vegetation in that area is a short, light weed cover, and not a dense undergrowth. Because of the unfertile nature of the soil in its present condition, I do not believe that additional reseedings with rye-grass will prove to be very effective until some sort of soil conditioning is implimented. It will probably take several years for natural revegetation to adequately cover the site.

If you have any questions or if I can be of further assistance, please contact me by phone or at the above address.

1000年 金色色 海色基础

" Very truly yours,

un

Walter Leuchak

Environmental Engineer

NL:mmc

cc: Terry Fabian

AR100108